



# Fresh Air Fan Bracket



cut sharp edges at  $45^\circ$  angle  
each corner



Bend  $\frac{1}{4}$ " for stiffness. More would be interference with bilge fan motor housing

